

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error	Ref #
84	BRS	23756	stepping adj motor	US-PGPU B; USPA T	2005/ 06/08 15:52				S84
85	BRS	1704	S84 with phase	US-PGPU B; USPA T	2005/ 06/08 15:52				S85
86	BRS	25	S85 with alignment	US-PGPU B; USPA T	2005/ 06/08 16:01				S86
87	BRS	1	"6704024".pn.	US-PGPU B; USPA T	2005/ 06/08 16:01				S87
88	BRS	3	"6141110"	US-PGPU B; USPA T	2005/ 06/23 16:47				S88
89	BRS	1	("4707649").PN.	US-PGPU B; USPA T; USOC R	2005/ 06/23 16:49				S89

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors	Ref #
90	BRS	6	((stepping or step or stepper) near2 motor) with (phase near3 alignment)	US-PGPU B; USPA T; USOC R	2005/ 06/23 17:00				S90
91	BRS	25	((stepping or step or stepper) near2 motor) same (phase near3 alignment)	US-PGPU B; USPA T; USOC R	2005/ 06/23 17:00				S91
92	BRS	19	S91 not S90	US-PGPU B; USPA T; USOC R	2005/ 06/23 17:00				S92
93	BRS	189	((step\$4 near3 motor) and phase and align\$4).clm.	US-PGPU B; USPA T	2005/ 06/24 14:17				S93
94	BRS	10	((step\$4 near3 motor) and phase and align\$4 and clock).clm.	US-PGPU B; USPA T	2005/ 06/24 14:20				S94

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error	Ref #
95	BRS	2	((step\$4 near3 motor) and phase and align\$4 and clock and power).clm.	US-PGPU B; USPA T	2005/ 06/24 14:21				S95
96	BRS	2	((step\$4 near3 motor) same phase same align\$4 same clock same power)	US-PGPU B; USPA T	2005/ 06/24 14:27				S96
97	BRS	8	((step\$4 near3 motor) same phase same align\$4 same clock)	US-PGPU B; USPA T	2005/ 06/24 14:27				S97
98	BRS	3	("4214194").URPN.	USPA T	2005/ 06/24 14:34				S98
99	BRS	1	"4706008".pn.	USPA T	2005/ 06/24 14:34				S99